


## Overview

# **Arburg double pump, AKP28 + AKP10 / R902433775, R902471919 / A10VS0 28 DFR1/31R- PPA12KB2-S1894, A10VS0 10 DFR1/52R-VSA14N00- S2679**

Arburg

**Product number:** 111002



### Price

**€2,730.00\***

Prices excl. VAT plus shipping costs



## Description

Arburg double axial pump AKP28 + AKP10

- removed from Arburg Allrounder 275 V 250 - 30
- removed from running machine
- fully functional

manufacturer: Arburg

type: AKP28 + AKP10

spare part no.: 250.957

manufacturer no.: R902433775, R902471919

Type code: A10VS0 28 DFR1/31R-PPA12KB2-S1894, A10VS0 10 DFR1/52R-VSA14N00-S2679

The number before the first slash describes the device series. For this reason, this digit of the type code on your old spare part may differ. If you have any questions, please do not hesitate to contact us.

## Product information

**condition:**

gebraucht